

LIGHT PROTECTION COVERS

THE IMPORTANCE OF MANUFACTURER APPROVED BARRIERS



Compatible with VistaScan Mini Plus



Compatible with VistaScan Mini View

- Created with the patient's needs in mind
- Does not compromise image quality
- Extends the service life of plates
- Contains high quality material composition
- Does not have any translucent areas

Thank you for your purchase and use of the VistaScan unit from Dürr Dental. The Dürr Dental Light Protection Covers are the manufacturer approved barrier sleeves to accompany your VistaScan unit.

The Dürr Dental Light Protection Covers were created in order to **maximise the service life of your VistaScan and ensure continued superior image quality** – hence the name light protection vs barrier.

The Dürr Dental Light Protection Covers are also **created with the patient's needs in mind** as they encompass:

- Health approved material
- Soft, pleasant feeling in the mouth
- 100% hygienically tight
- Very high light resistance for excellent image quality
- Simple handling

The manufacturers have perfectly coordinated their image plates and protective covers.

Always follow the manufacturer's instructions when ordering protective covers as this ensures that the highest quality levels are maintained for the diagnostic results.

Furthermore, it also **reduces material costs by extending the service life of the plates** because a major drawback of using generic sleeves is that the inferior adhesive sealant can transfer to the belt drive which affects image quality and increases maintenance repairs. Additionally, certain generic covers may contain latex which is an allergen for some patients.

LIGHT PROTECTION COVERS

THE IMPORTANCE OF MANUFACTURER APPROVED BARRIERS



Light Protection Cover Material Comparison



Generic Barrier Sleeve



Durr Dental Light Protection Cover

Some possible disadvantages of using generic barrier sleeves:

- Rough surface, bad seams
- Sealing capabilities inferior
- More difficult to feed the film into VistaScan units
- Bad sliding performance (danger that the sleeve will be retracted into scanner)
- Excess adhesive can cause plate contamination

Laserpointer Test Comparison



Generic Barrier Sleeve



Durr Dental Light Protection Cover

Note: The translucent area within the red circle found when performing a laserpointer test

To order the Durr Dental Light Protection Covers, please visit www.henryschein.com.au or contact Henry Schein on 1300 65 88 22

DU-213007000	Light Protection Cover	Size 0 x 100	VistaScan Barrier Envelopes
DU-213007100	Light Protection Cover	Size 1 x 100	VistaScan Barrier Envelopes
DU-213007200	Light Protection Cover	Size 2 x 300	VistaScan Barrier Envelopes
DU-213007255	Light Protection Cover	Size 2 x 1000	VistaScan Barrier Envelopes
DU-213007300	Light Protection Cover	Size 3 x 100	VistaScan Barrier Envelopes
DU-213007400	Light Protection Cover	Size 4 x 100	VistaScan Barrier Envelopes